





Box Pairing

Smartphone control of welding unit.





Box Pairing

The welding unit connects to the smartphone using Bluetooth.




Photo Evidence

Images can be taken to show that the fitting has been set up and clamped correctly.



Data Transmission

Welding data is uploaded after each weld is completed.



Data file is transferred to the phone





Data Transmission

The data is then automatically uploaded.



Data Transmission


If there is no mobile signal, files will upload when signal returns.






Emailing Data

Data will be sent to your pre-configured email addresses.




Emailing Data

The email contains a summary and the attached CZIP file.




Data files are opened with the CalderSafe Weld Analyser.






Obtain the CalderSafe® Weld Analyser only from Caldervale Technology


Graph with 124 point data plot of Supply Voltage, Output Voltage and Output Current.




Graph can be shown in full screen mode.




For barcode welds, the barcode can be recreated and printed out.




Data files are backed up onto the PC and organised into folders.



Google Maps are integrated to give visual reference of location.



Mass data can be analysed through pie charts and bar charts.



Get the App

Find the CalderSafe Android app on the Google Play Store®





Contact Us

For more information contact: info@caldertech.com



